


FILE COPY



SITE REMEDIATION REPORT


**Frazier Property
405 Lee Avenue
Crystal Springs, Mississippi**

Prepared for

BorgWarner Inc.

February 2002

FILE COPY



SITE REMEDIATION REPORT

**Frazier Property
405 Lee Avenue
Crystal Springs, Mississippi**


Prepared for

BorgWarner Inc.

February 2002

SITE REMEDIATION REPORT

Frazier Property
405 Lee Avenue
Crystal Springs, Mississippi



Prepared for

BorgWarner Inc.

FILE COPY

Prepared by

MARTIN&SLAGLE GeoEnvironmental Associates, LLC
PO Box 1023
Black Mountain, North Carolina

February 2002

A handwritten signature in cursive script, appearing to read "Robert L. Martin", written over a horizontal line.

Robert L. Martin, P.G.
Project Manager

A handwritten signature in cursive script, appearing to read "Christine E. Slagle", written over a horizontal line.

Christine E. Slagle
Senior Scientist

TABLE OF CONTENTS

SITE REMEDIATION REPORT

**Frazier Property
405 Lee Avenue
Crystal Springs, Mississippi**

1.0	Executive Summary	1-1
2.0	Introduction	2-1
2.1	Background	2-1
2.2	Site Description	2-2
2.3	Previous Investigative Activities	2-3
3.0	Sampling Program – Location and Rationale	3-1
4.0	Analytical Program	4-1
5.0	Remediation and Disposal	5-1
6.0	Summary and Conclusions	6-1

**SITE MAPS
TABLES**

APPENDIX 1	Analytical Data Tables
APPENDIX 2	Chains of Custody
APPENDIX 3	Manifests
APPENDIX 4	Photographs
APPENDIX 5	Data Validation