

SITE CHARACTERIZATION ASSESSMENT REPORT



**Mid South Leasing Property
112 and 114 Brent Street
Crystal Springs, Mississippi**


Prepared for

BorgWarner Inc.

July 2004

**GeoEnvironmental
Associates, LLC**

MARTIN & SLAGLE



**SITE CHARACTERIZATION ASSESSMENT
REPORT**



**MidSouth Leasing Property
112 and 114 Brent Street
Crystal Springs, Mississippi**

Prepared for
BorgWarner Inc.

Prepared by
MARTIN & SLAGLE GEOENVIRONMENTAL ASSOCIATES, LLC
208A SUTTON AVE.
PO Box 1023
BLACK MOUNTAIN, NC 28711

July 2004

A handwritten signature in cursive script, appearing to read "Robert L. Martin", written over a horizontal line.

Robert L. Martin, L.G.
Project Manager

A handwritten signature in cursive script, appearing to read "Christine E. Slagle", written over a horizontal line.

Christine Slagle
Principal Scientist

A handwritten signature in cursive script, appearing to read "Richard Beale", written over a horizontal line.

Richard Beale
Senior Associate

TABLE OF CONTENTS

SECTION 1.0 EXECUTIVE SUMMARY	1-1
--------------------------------------	------------

SECTION 2.0 INTRODUCTION

2.1	Site Description	2-1
2.2	Background	2-2
2.3	Site Characterization Objectives	2-3
2.4	Current and Former Land Use	2-5
2.5	Summary of Previous Work at the MSL Property	2-6

SECTION 3.0 INVESTIGATIVE ACTIVITIES

3.1	Summary of Work Performed	3-1
3.2	Property and Sample Point Survey	3-2
3.3	Geophysical Survey	3-3
	3.3.1 Electromagnetic Conductivity Survey	3-3
	3.3.2 2D Resistivity Model Survey	3-4
3.4	Drilling and Soil Sampling	3-5
3.5	Direct Push and Hand Auger Soil Sampling	3-6
3.6	Test Pits	3-8

SECTION 4.0 SITE CHARACTERIZATION

4.1	Source Area	4-1
4.2	Regional Geology	4-1
4.3	Regional Hydrogeology	4-2
4.4	Study Area Geology	4-3
4.5	Study Area Hydrogeology	4-3

SECTION 5.0 NATURE AND EXTENT OF CONTAMINATION

5.1	Mid South Leasing Property	5-1
	5.1.1 Rotary Auger Soil Sampling Results	5-1
	5.1.2 Direct Push and Hand Auger Soil and Sediment Sampling	5-2
	5.1.3 Test Pit Installation and Sampling	5-3
5.2	Raymond Lamar, Sr. Property	5-3
5.3	Raymond Lamar, Jr. Property	5-5

TABLE OF CONTENTS (cont.)

SECTION 6.0 CONTAMINANT FATE AND TRANSPORT	6-1
6.1 Potential Migration Routes	6-1
6.2 Contaminant Concentrations	6-1
6.2.1 Mid South Leasing Property	6-1
6.2.2 Raymond Lamar, Sr. Property	6-3
6.2.3 Raymond Lamar, Jr. Property	6-3
6.3 Contaminant Migration	6-3

SECTION 7.0 QUALITY ASSURANCE/QUALITY CONTROL RESULTS 7-1

7.1 Site Characterization Assessment Objectives	7-1
7.2 Analytical Methods	7-2
7.3 Key Personnel	7-2
7.4 Quality Assurance Objectives for Data	7-4
7.5 Sample Control and Field Records	7-5
7.5.1 Sample Identification	7-5
7.5.2 Chain of Custody Procedures	7-5
7.5.3 Field Records	7-5
7.6 Laboratory Quality Assurance/Quality Control	7-6
7.7 Data Review and Validation	7-6

SECTION 8.0: SUMMARY AND CONCLUSIONS 8-1

8.1 Geophysical Survey	8-1
8.2 Installation of Soil Borings in Fill Area Using Rotary Auger Drilling	8-1
8.3 Direct Push and Hand Auger Soil Sampling	8-3
8.4 Conclusion	8-5

FIGURES

- Figure 1 - Vicinity Map
- Figure 2 - Study Area Map
- Figure 3 - Map of Sample Locations for June 2002 Initial Assessment
- Figure 4 - Map of Protective Liner Boundaries & Test Pit Locations
- Figure 5 - Hollow Stem Auger Boring Locations Map
- Figure 6 - Map of Direct Push & Hand Auger Sample Locations

TABLE OF CONTENTS (cont.)

TABLES

Table 1 - Initial Assessment Data from June 2002

Table 2 - Hollow Stem Auger Samples

Table 3 - Mid South Leasing Direct Push & Hand Auger Samples

Table 4 - Raymond Lamar, Sr. Property Direct Push & Hand Auger Samples

Table 5 - Raymond Lamar, Jr. Property Hand Auger Samples

Table 6 - Test Pit Samples

Table 7 - Quality Control Samples

APPENDICES

Appendix 1 - Photo Log

Appendix 2 - Schnabel Engineering Geophysical Report

Appendix 3 - Rotary Auger Drilling Boring Logs

Appendix 4 - Summary of Field & Laboratory Data Results for Initial Assessment

Appendix 5 - Summary of Current Site Characterization Field & Laboratory Data Results

Appendix 6 - Gradient Corporation Data Validation Report