

## Ball Float Vent Orifices

If the vent orifice hole is not located near the top of the tank, MDEQ will allow it to be plugged and a new hole drilled in the vent the same size as the original manufacturer's hole and at the proper location near the top of the tank. This is the only thing that is allowed to be done to a ball float valve that does not require an alternative overfill device to be used.

A handwritten signature in cursive script that reads "Mike Pigford".

Mike Pigford  
4/24/19