

Environ Pipe or Total Containment Pipe replaced inside of Chase Pipe considered a repair

“Since Environ and Total Containment pipe has had known reliability issues, MDEQ will allow it to be replaced with double wall pipe without adding water tight sumps with no interstitial monitoring requirement as long as there is an existing chase pipe in place. Since the chase pipe is not being replaced, we interpret this to be a repair, not a 100% replacement. We will require the owner to notify us when this is done so that we can change registration to show the new primary pipe. (We will need to input the install date in Muster to be prior to 10/1/2008 with comments in registration giving the actual date of installation)”

Notice of Planned Install should be submitted checking “New piping at an existing facility to partially replace (repair) existing piping” with copy of this letter attached and info showing what pipe was installed as part of the repair and the date of the repair. Submit testing of the new pipe used in the repair.

Mike Pigford

11/1/16

Rev A – 11/28/16