

PHOTOGRAPH LOG

Hercules Hattiesburg, MS Site



Photograph: 1

Description:
Brick sign before
removal.

Date:
6/9/2022



Photograph: 2

Description:
Brick sign before
removal.

Date:
6/9/2022

PHOTOGRAPH LOG

Hercules Hattiesburg, MS Site



Photograph: 3

Description:
Brick sign area after removal.

Date:
6/9/2022



Photograph: 4

Description:
Brick sign area after removal.

Date:
6/9/2022

PHOTOGRAPH LOG

Hercules Hattiesburg, MS Site



Photograph: 5

Description:
Pole barn property
before mowing.

Date:
6/9/2022



Photograph: 6

Description:
Pole barn property
before mowing.

Date:
6/9/2022

PHOTOGRAPH LOG

Hercules Hattiesburg, MS Site



Photograph: 7

Description:
Pole barn property
before mowing.

Date:
6/9/2022



Photograph: 8

Description:
Pole barn property
after
mowing.

Date:
6/10/2022

PHOTOGRAPH LOG

Hercules Hattiesburg, MS Site



Photograph: 9

Description:

Pole barn property after mowing. The steel pole on the left side of the photo was removed after the photograph was taken.

Date:

6/10/2022



Photograph: 10

Description:

Pole barn property after mowing. The steel pole in the center of the photo was removed after the photograph was taken.

Date:

6/10/2022

PHOTOGRAPH LOG

Hercules Hattiesburg, MS Site



Photograph: 11

Description:
Impoundment Basin
cap before mowing.

Date:
6/10/2022



Photograph: 12

Description:
Impoundment Basin
cap before mowing.

Date:
6/10/2022

PHOTOGRAPH LOG

Hercules Hattiesburg, MS Site



Photograph: 13

Description:
Impoundment Basin
cap after mowing.

Date:
6/10/2022



Photograph: 14

Description:
Impoundment Basin
cap after mowing.

Date:
6/10/2022

PHOTOGRAPH LOG

Hercules Hattiesburg, MS Site



Photograph: 15

Description:
Impoundment Basin
cap after mowing.

Date:
6/10/2022