

Summary Information On Underground Storage Tanks (USTs)

10/01/2017 09/30/2018

General Information

Total Number of UST Facilities: 3,003
Total Number of USTs: 8,109

Summary Information For Inspections

Number Of UST Facilities Inspected: 1141
Percent Compliance (Combined Measure): 68

Note: Tank, facility, and on-site inspection information is based on USTs regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12, except for those tanks identified in 40 CFR 280.10(b) as excluded USTs. USTs deferred in 40 CFR 280.10(c) and those used for emergency power generation are included as part of the public record.

Summary Information For Releases

Number Of Confirmed UST Releases: 149

Summary Information For Release Sources and Causes

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	11	12.0	0	0.0	0	0.0	2	10.0	1	100.0	0	0.0	0	0.0	7	10.0
Piping	20	21.0	0	0.0	0	0.0	11	1100.0	0	0.0	0	0.0	1	50.0	8	12.0
Dispenser	9	9.0	1	50.0	0	0.0	5	25.0	0	0.0	0	0.0	0	0.0	3	4.0
STP	7	7.0	0	0.0	0	0.0	2	10.0	0	0.0	0	0.0	0	0.0	5	7.0
Delivery Problem	1	1.0	1	50.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Other	1	1.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	50.0	0	0.0
Unknown	46	48.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	46	67.0
Totals	95	100	2	100	0	100	20	100	1	100	0	100	2	100	69	100

= number, % = percent of total number

For site specific information, please contact MDEQ Public Information Officer at 601-961-5118

Report Date: 12/19/2018