

**KUHLMAN ELECTRIC CORPORATION  
PLANT SITE REMEDIATION REPORT**

**APPENDIX 1  
On-Site Laboratory  
Analytical Data Sheets  
With Chains of Custody**


**Volume V**



**Kuhlman Electric Corporation  
Crystal Springs, Mississippi**

**Prepared for  
BorgWarner Inc.**

**June 2004**



February 10, 2003

Robert Martin  
Martin & Slagle, LLC  
P.O. Box 1023  
Black Mountain, NC 28711

Dear Mr. Martin,

Enclosed is the Technical Memorandum for work completed at the former Borg Warner and current Kuhlman Electric facility in Crystal Springs, Mississippi during the month of January. If you have any questions concerning this information, please give me a call.

Sincerely,

Richard Johnson

Enclosure

Environmental Chemistry Consulting Services, Inc.

2525 Advance Road • Madison, WI 53718 • Phone (608) 221-8700 • FAX (608) 221-4889

**Technical Memorandum**  
**Borg Warner / Kuhlman Electric**  
**Crystal Springs, Mississippi**