




PLATE 1

Record of a hole and adjacent roadcut on east side of U.S. Highway 61 bypass at footage 23,200 (figure 6), showing 108 feet of loess zoned on the basis of physical, chemical, electrical, and radiation criteria.