

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY

JANUARY 3, 2003

PHOTOGRAPHS ILLUSTRATING VARIOUS
PROBLEMS OBSERVED IN THE FIELD WITH
THERMOPLASTIC FLEXIBLE PIPING SYSTEMS






FITTINGS/FLEX CONNECTORS TWISTED/MISALIGNED



Citgo
Charleston, WVA
TCI 1503

PIPING OVER BENT



PIPING KINKED



OUTER JACKET GROWING

